Accident / Incident Report Closed




Unit/Department	Process Area		Site			Rep	ort Numb		
South Operation-Elyria	General Catal	lyst – Building	19 ELY	ELYRIA			0084-SOPS-15-0050		
Report Date	Incident Date			lent Time			ied From		
04/16/2015	04/15/2015	• • • •		O PM		00p			
		· · · · · · · · · · · · · · · · · · ·							
Incident Location				n Leader / Si	upervisor		orted By		
Building #9 Dust collector	· f'		Brian Beller			Brian Beller			
Title of Event (Limit to 90 cl		Cate	egory			sion / Bus group Co			
Powder discharge from th the PK Blender	building #9 fo	1.—	Safety & Heal nvironmenta		cc /	G-CCP	an field of sole to a con-		
Incident Classification									
Near Miss	☐ Prope	erty Loss		□ c	ontractor				
Process Safety	Citatio	on / NOV		□ co	ontractor	Injury / Iline	ess		
🔲 Injury / Iliness	Healti	h Exposure		□ co	ontract In	jury / Illnes:	8		
Spill / Release	Inspe	ection		☐ P8	SM				
Permit / Regulatory Devi		r Incident		Plant Upset					
∐ Fire	_	Occupational			IS Mana	gement Sys	stem Failu	are	
Odor Complaint	☐ RMP			∐ Ot	her				
Describe Event / What Happ	ened				····				
operator turn off the dust of Immediate Corrective Action Turned off the Dust Collec	or Response								
Immediate Cause		·							
unknown			* WWW.*****************			,			
Spill Release Type(s)	Non RQ Spill / E	Release							a to a saddraw t
Chemical(s) Involved		CAS#		Phy. State	Air	Land	Water	Contmt	Units
Al 3921		NA		Dust	1	0	0	0	lbs
Disposition of Material	loss to air				r an artata				
Weather Conditions	Skies:	Temperature:			Wi	d Direction:		Wind Speed:	
Agencies Notified	L								
F) Follow up (I) Immediate	Person Called		Notified By		Date/Time Notified				
Anthony Decker		Tim Anglin			4/16/2015 8:27:37 Tin AM		Tim Angl	m Anglin	
The state of the s									
Cause Narrative									
Dusting coming from the dused for the PK blender.	lust collector blow	er discharge _l	pipe on	the west sid	e of the	building #	9. This du	ıst collect	tor is
Contributing Causes		Root/Priman	/ Causes	ivia de Camara es L			2.202.00		
Used dust collection bags were reinstalled in dust collector bag house.		1 (OOD) Tilliary				31 - Repair Implemtation LTA			
dust collector bag house. Current baghouse systems of		28 - Equipme Reliability Pro Implementati	ent ogram	29 - Correc Maintenand		31 - Repa	ir Implem	itation LTA	\

Printed: 09/28/2016


Explanation of Root Causes 31 - Dust bag were reused instead of installing new ones. This caused a poor seal on the bags, leading to the dust discharge. Any known or potential off-site impacts? PSM Incident? No Estimated Cost: 3,000.00 USD No Investigation Team Brian Beller; Robert Urig VC VE Corrective Action(s) to prevent recurrence Responsible Person Target Final Closed Re Re m Date Date q q N 05/30/2015 04/24/2015 Ν 1 Install new dust collector bags in baghouse for Robert bldg #9 dust collector. Urig/BASF-CATALYSTS/BASF 2 Assign an engineer to investigate bag monitoring William D 09/26/2015 09/21/2015 Ν systems for dust collectors for the Elyria plant. Add a capital project to the list to execute a Deisenroth/BASF-CATALYSTS/BAS project if a suitable type is found

Approved By:	
Manager / Dept. Head	Leon Zavodnik 04/26/2015 11:29 AM
EHS Unit Coordinator	Valerie Topete 05/04/2015 11:48 AM
Safety & I.H.	Nancy Gallagher 04/30/2015 07:42 AM
	Confidential
l	


Printed: 09/28/2016 Page: 2



CONFIDENTIAL



CONFIDENTIAL BASF_114_000039



CONFIDENTIAL BASF_114_000040

CONFIDENTIAL